# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, January 5, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | December Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 12.6 | 8.25 | 0.08 | 3.45 | | 0.73 | 0.01 | 68 | 98 | 0.4 | 0.005 | 1 | 280 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 13.0 | 8.35 | 0.07 | 3.20 | | 0.67 | 0.06 | 70 | 98 | 0.7 | 0.005 | 1 | 285 | Absent | |
| Chorro | | | | | | | | | | | | | | | 124 |
| Lopez T/O | | | | | | | | | | | | | | | 0 |
| Guadalupe T/O | 16.1 | 8.46 | 0.07 | 2.94 | | 0.65 | 0.09 | 74 | 106 | 0.7 | 0.006 | 1 | 298 | Absent | 32 |
| Santa Maria T/O | 15.9 | 8.47 | 0.06 | 2.88 | | 0.66 | 0.10 | 76 | 106 | 0.6 | 0.006 | 1 | 301 | Absent | 342 |
| Golden State T/O | | | | | | | | | | | | | | | 5 |
| Tank Site #5 | 16.2 | 8.44 | 0.08 | 2.54 | | 0.61 | 0.14 | 78 | 110 | 0.7 | 0.012 | 1 | 312 | Absent | |
| Vandenberg T/O | 15.9 | 8.47 | 0.07 | 2.81 | | 0.53 | 0.00 | 80 | 108 | 0.6 | 0.006 | 1 | 311 | Absent | 227 |
| Tank Site #7 | 17.1 | 8.98 | 0.06 | 1.37 | | 0.33 | 0.02 | 78 | 110 | 0.5 | 0.008 | 1 | 362 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 7.3 **MG**

*Samples Taken:* 01/05/2026
*Samples Analyzed:* 1/8/2026 10:47:00 AM
*Sampler:* James Thompson, Sean Rog
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 01/09/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, January 12, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | December Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 11.5 | 8.23 | 0.05 | 3.42 | | 0.67 | 0.02 | 68 | 102 | 0.8 | 0.006 | 1 | 293 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 13.2 | 8.29 | 0.07 | 3.11 | | 0.68 | 0.08 | 82 | 102 | 0.8 | 0.005 | 1 | 292 | Absent | |
| Chorro | 14.5 | 8.36 | 0.05 | 3.09 | | 0.65 | 0.05 | 78 | 102 | 0.7 | 0.006 | 1 | 288 | Absent | 124 |
| Lopez T/O | 16.2 | 8.38 | 0.06 | 2.89 | | 0.63 | 0.07 | 74 | 100 | 0.5 | 0.005 | 1 | 286 | Absent | 0 |
| Guadalupe T/O | 16.5 | 8.46 | 0.07 | 2.90 | | 0.64 | 0.08 | 72 | 100 | 0.5 | 0.006 | 1 | 285 | Absent | 32 |
| Santa Maria T/O | 16.5 | 8.45 | 0.07 | 2.83 | | 0.64 | 0.09 | 70 | 100 | 0.4 | 0.007 | 1 | 284 | Absent | 342 |
| Golden State T/O | | | | | | | | | | | | | | | 5 |
| Tank Site #5 | 16.4 | 8.48 | 0.06 | 2.49 | | 0.56 | 0.09 | 70 | 100 | 0.4 | 0.016 | 1 | 283 | Absent | |
| Vandenberg T/O | 16.6 | 8.45 | 0.06 | 2.76 | | 0.52 | 0.00 | 70 | 104 | 0.4 | 0.006 | 1 | 285 | Absent | 227 |
| Tank Site #7 | 16.6 | 8.94 | 0.07 | 1.35 | | 0.31 | 0.05 | 74 | 108 | 0.4 | 0.005 | 1 | 362 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 8.0 **MG**

*Samples Taken:* 01/12/2026
*Samples Analyzed:* 1/15/2026 11:58:00 AM
*Sampler:* James Thompson, Sean Rog
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 01/15/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Tuesday, January 20, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | December Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 12.4 | 8.19 | 0.05 | 3.32 | | 0.73 | 0.05 | 74 | 116 | 0.4 | 0.006 | 1 | 333 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 12.8 | 8.28 | 0.07 | 3.09 | | 0.60 | 0.06 | 76 | 112 | 0.4 | 0.006 | 1 | 313 | Absent | |
| Chorro | 14.0 | 8.33 | 0.09 | 3.06 | | 0.61 | 0.09 | 74 | 108 | 0.3 | 0.005 | 1 | 311 | Absent | 124 |
| Lopez T/O | 14.7 | 8.37 | 0.07 | 2.99 | | 0.57 | 0.06 | 72 | 108 | 0.3 | 0.006 | 1 | 306 | Absent | 0 |
| Guadalupe T/O | 15.6 | 8.40 | 0.05 | 2.86 | | 0.64 | 0.08 | 70 | 108 | 0.3 | 0.006 | 1 | 301 | Absent | 32 |
| Santa Maria T/O | 15.7 | 8.38 | 0.06 | 2.72 | | 0.63 | 0.08 | 70 | 106 | 0.3 | 0.005 | 1 | 300 | Absent | 342 |
| Golden State T/O | | | | | | | | | | | | | | | 5 |
| Tank Site #5 | 16.1 | 8.38 | 0.07 | 2.36 | | 0.55 | 0.10 | 70 | 106 | 0.4 | 0.016 | 1 | 296 | Absent | |
| Vandenberg T/O | 15.9 | 8.38 | 0.05 | 2.61 | | 0.50 | 0.00 | 72 | 108 | 0.4 | 0.006 | 1 | 296 | Absent | 227 |
| Tank Site #7 | 17.0 | 8.85 | 0.06 | 1.06 | | 0.33 | 0.12 | 72 | 110 | 0.4 | 0.010 | 1 | 362 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 7.3 **MG**

*Samples Taken:* 01/20/2026

*Samples Analyzed:* 1/22/2026 10:40:00 AM

*Sampler:* David Bazzell, Sean Rogers

*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 01/23/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, January 26, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | December Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 12.3 | 8.32 | 0.08 | 3.40 | | 0.72 | 0.01 | 66 | 106 | 0.4 | 0.005 | 1 | 317 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 12.8 | 8.26 | 0.08 | 3.07 | | 0.62 | 0.09 | 74 | 112 | 0.5 | 0.004 | 1 | 341 | Absent | |
| Chorro | 14.0 | 8.30 | 0.07 | 2.98 | | 0.58 | 0.08 | 74 | 122 | 0.5 | 0.005 | 1 | 345 | Absent | 124 |
| Lopez T/O | 14.6 | 8.36 | 0.06 | 2.98 | | 0.60 | 0.09 | 76 | 120 | 0.4 | 0.005 | 1 | 345 | Absent | 0 |
| Guadalupe T/O | 15.9 | 8.39 | 0.08 | 2.84 | | 0.64 | 0.09 | 76 | 120 | 0.4 | 0.006 | 1 | 341 | Absent | 32 |
| Santa Maria T/O | 16.7 | 8.42 | 0.06 | 2.84 | | 0.63 | 0.08 | 76 | 118 | 0.4 | 0.005 | 1 | 337 | Absent | 342 |
| Golden State T/O | | | | | | | | | | | | | | | 5 |
| Tank Site #5 | 15.4 | 8.41 | 0.06 | 2.41 | | 0.56 | 0.12 | 74 | 114 | 0.4 | 0.027 | 1 | 323 | Absent | |
| Vandenberg T/O | 15.5 | 8.42 | 0.05 | 2.69 | | 0.54 | 0.03 | 74 | 112 | 0.3 | 0.010 | 1 | 318 | Absent | 227 |
| Tank Site #7 | 15.9 | 8.84 | 0.07 | 0.91 | | 0.30 | 0.11 | 72 | 110 | 0.4 | 0.022 | 1 | 363 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 7.5 **MG**

*Samples Taken:* 01/26/2026

*Samples Analyzed:* 1/27/2026 1:32:00 PM

*Sampler:* Adrian Arguilles, Sean Roger

*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 01/29/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, February 2, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | January Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 13.9 | 8.19 | 0.09 | 3.38 | | 0.73 | 0.05 | 66 | 104 | 0.6 | 0.005 | 1 | 305 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 12.9 | 8.31 | 0.08 | 3.07 | | 0.61 | 0.08 | 64 | 102 | 0.6 | 0.006 | 1 | 307 | Absent | |
| Chorro | 14.1 | 8.34 | 0.09 | 2.94 | | 0.58 | 0.09 | 66 | 102 | 0.5 | 0.005 | 1 | 306 | Absent | 120 |
| Lopez T/O | 14.8 | 8.37 | 0.07 | 2.91 | | 0.55 | 0.05 | 66 | 102 | 0.5 | 0.004 | 1 | 307 | Absent | 20 |
| Guadalupe T/O | 16.4 | 8.43 | 0.06 | 2.79 | | 0.62 | 0.08 | 66 | 104 | 0.4 | 0.005 | 1 | 309 | Absent | 19 |
| Santa Maria T/O | 16.2 | 8.42 | 0.07 | 2.81 | | 0.63 | 0.10 | 66 | 106 | 0.4 | 0.006 | 1 | 311 | Absent | 349 |
| Golden State T/O | | | | | | | | | | | | | | | 1 |
| Tank Site #5 | 15.7 | 8.41 | 0.09 | 2.50 | | 0.59 | 0.11 | 68 | 108 | 0.4 | 0.014 | 1 | 320 | Absent | |
| Vandenberg T/O | 15.5 | 8.36 | 0.07 | 2.98 | | 0.55 | 0.03 | 68 | 108 | 0.4 | 0.011 | 1 | 328 | Absent | 226 |
| Tank Size #7 | 15.4 | 8.82 | 0.06 | 0.72 | | 0.26 | 0.10 | 72 | 106 | 0.5 | 0.066 | 1 | 364 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 8.9 **MG**

*Samples Taken:* 02/02/2026
*Samples Analyzed:* 2/5/2026 12:23:00 PM
*Sampler:* Cody Weinberg, Sean Roger
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 02/06/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, February 9, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | January Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 14.0 | 8.21 | 0.06 | 3.20 | | 0.67 | 0.00 | 70 | 102 | 0.8 | 0.005 | 1 | 280 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 13.3 | 8.27 | 0.08 | 2.91 | | 0.60 | 0.09 | 68 | 102 | 0.9 | 0.005 | 1 | 293 | Absent | |
| Chorro | 14.4 | 8.33 | 0.07 | 2.91 | | 0.60 | 0.09 | 70 | 104 | 0.8 | 0.007 | 1 | 298 | Absent | 120 |
| Lopez T/O | 14.8 | 8.34 | 0.07 | 2.78 | | 0.58 | 0.10 | 70 | 100 | 0.7 | 0.007 | 1 | 302 | Absent | 20 |
| Guadalupe T/O | 15.6 | 8.38 | 0.07 | 2.76 | | 0.64 | 0.10 | 70 | 96 | 0.6 | 0.006 | 1 | 306 | Absent | 19 |
| Santa Maria T/O | 15.7 | 8.40 | 0.06 | 2.67 | | 0.64 | 0.11 | 72 | 100 | 0.5 | 0.006 | 1 | 307 | Absent | 349 |
| Golden State T/O | | | | | | | | | | | | | | | 1 |
| Tank Site #5 | 15.7 | 8.40 | 0.06 | 2.34 | | 0.56 | 0.12 | 70 | 104 | 0.5 | 0.021 | 1 | 309 | Absent | |
| Vandenberg T/O | 15.6 | 8.39 | 0.08 | 2.61 | | 0.52 | 0.02 | 68 | 106 | 0.4 | 0.009 | 1 | 311 | Absent | 226 |
| Tank Size #7 | 16.9 | 8.70 | 0.06 | 0.39 | | 0.10 | 0.04 | 74 | 108 | 0.5 | 0.199 | 1 | 364 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 6.8 **MG**

*Samples Taken:* 02/09/2026
*Samples Analyzed:* 2/12/2026 10:38:00 AM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 02/18/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Tuesday, February 17, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | January Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 12.8 | 8.36 | 0.05 | 3.29 | | 0.73 | 0.05 | 70 | 92 | 1.0 | 0.007 | 1 | 251 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 13.7 | 8.31 | 0.06 | 3.00 | | 0.70 | 0.13 | 70 | 98 | 1.1 | 0.005 | 1 | 260 | Absent | |
| Chorro | | | | | | | | | | | | | | | 120 |
| Lopez T/O | 14.8 | 8.41 | 0.07 | 2.92 | | 0.66 | 0.14 | 74 | 96 | 1.0 | 0.006 | 1 | 264 | Absent | 20 |
| Guadalupe T/O | 15.6 | 8.46 | 0.07 | 2.69 | | 0.68 | 0.15 | 76 | 100 | 0.9 | 0.007 | 1 | 269 | Absent | 19 |
| Santa Maria T/O | 15.8 | 8.43 | 0.10 | 2.61 | | 0.66 | 0.12 | 76 | 100 | 0.9 | 0.007 | 1 | 272 | Absent | 349 |
| Golden State T/O | | | | | | | | | | | | | | | 1 |
| Tank Site #5 | 15.6 | 8.45 | 0.08 | 2.24 | | 0.58 | 0.14 | 78 | 102 | 0.8 | 0.033 | 1 | 279 | Absent | |
| Vandenberg T/O | 14.4 | 8.43 | 0.10 | 2.62 | | 0.52 | 0.02 | 78 | 102 | 0.8 | 0.009 | 1 | 283 | Absent | 226 |
| Tank Size #7 | 16.2 | 8.69 | 0.11 | 0.04 | | 0.03 | 0.02 | 80 | 108 | 0.5 | 0.241 | 1 | 364 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 7.9 **MG**

*Samples Taken:* 02/17/2026
*Samples Analyzed:* 2/18/2026 2:37:00 PM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 02/20/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, March 2, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | February Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 15.7 | 8.32 | 0.10 | 3.53 | | 0.73 | 0.02 | 70 | 86 | 1.1 | 0.005 | 1 | 222 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 14.3 | 8.30 | 0.06 | 3.20 | | 0.61 | 0.05 | 74 | 90 | 1.1 | 0.006 | 1 | 234 | Absent | |
| Chorro | 14.9 | 8.36 | 0.12 | 3.11 | | 0.57 | 0.06 | 80 | 94 | 1.1 | 0.005 | 1 | 238 | Absent | 134 |
| Lopez T/O | 15.1 | 8.37 | 0.06 | 3.02 | | 0.59 | 0.08 | 82 | 94 | 1.0 | 0.006 | 1 | 241 | Absent | 105 |
| Guadalupe T/O | 15.4 | 8.44 | 0.08 | 2.95 | | 0.69 | 0.11 | 82 | 94 | 1.0 | 0.008 | 1 | 245 | Absent | 15 |
| Santa Maria T/O | 15.4 | 8.40 | 0.11 | 2.92 | | 0.68 | 0.10 | 80 | 92 | 1.0 | 0.007 | 1 | 245 | Absent | 306 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 15.5 | 8.29 | 0.09 | 2.03 | | 0.49 | 0.12 | 80 | 92 | 1.0 | 0.044 | 1 | 240 | Absent | |
| Vandenberg T/O | 15.1 | 8.28 | 0.08 | 2.25 | | 0.43 | 0.02 | 80 | 92 | 1.0 | 0.007 | 1 | 241 | Absent | 206 |
| Tank Size #7 | | | | | | | | | | | | | | | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 10.5 **MG**

*Samples Taken:* 03/02/2026

*Samples Analyzed:* 3/3/2026 3:02:00 PM

*Sampler:* Adrian Arguilles, Sean Roger

*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 03/10/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, March 9, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | February Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 17.0 | 8.23 | 0.06 | 3.31 | | 0.73 | 0.04 | 66 | 80 | 1.1 | 0.006 | 1 | 204 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 15.3 | 8.29 | 0.06 | 3.13 | | 0.65 | 0.05 | 68 | 82 | 1.3 | 0.005 | 1 | 208 | Absent | |
| Chorro | 15.9 | 8.34 | 0.08 | 3.03 | | 0.62 | 0.00 | 68 | 82 | 1.2 | 0.006 | 1 | 209 | Absent | 134 |
| Lopez T/O | 16.2 | 8.38 | 0.07 | 2.92 | | 0.61 | 0.08 | 70 | 84 | 1.1 | 0.006 | 1 | 212 | Absent | 105 |
| Guadalupe T/O | 16.5 | 8.41 | 0.11 | 2.81 | | 0.65 | 0.10 | 72 | 86 | 1.0 | 0.006 | 1 | 215 | Absent | 15 |
| Santa Maria T/O | 16.4 | 8.40 | 0.11 | 2.80 | | 0.64 | 0.09 | 74 | 86 | 1.0 | 0.006 | 1 | 215 | Absent | 306 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 16.0 | 8.35 | 0.07 | 2.01 | | 0.50 | 0.13 | 76 | 88 | 1.0 | 0.057 | 1 | 223 | Absent | |
| Vandenberg T/O | 15.3 | 8.31 | 0.07 | 2.13 | | 0.41 | 0.03 | 76 | 88 | 1.0 | 0.007 | 1 | 228 | Absent | 206 |
| Tank Size #7 | | | | | | | | | | | | | | | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 9.2 **MG**

*Samples Taken:* 03/09/2026
*Samples Analyzed:* 3/12/2026 8:20:00 AM
*Sampler:* Cody Weinberg, Joe Parent
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 03/12/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, March 16, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | February Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 19.0 | 8.39 | 0.05 | 3.25 | | 0.65 | 0.01 | 62 | 78 | 1.0 | 0.006 | 1 | 209 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 16.2 | 8.35 | 0.07 | 2.96 | | 0.55 | 0.05 | 64 | 80 | 1.2 | 0.005 | 1 | 208 | Absent | |
| Chorro | 16.9 | 8.38 | 0.08 | 2.86 | | 0.73 | 0.16 | 66 | 82 | 1.2 | 0.007 | 1 | 208 | Absent | 134 |
| Lopez T/O | 17.2 | 8.40 | 0.07 | 2.87 | | 0.53 | 0.09 | 66 | 82 | 1.1 | 0.007 | 1 | 208 | Absent | 105 |
| Guadalupe T/O | 17.5 | 8.42 | 0.09 | 2.75 | | 0.64 | 0.10 | 66 | 82 | 1.1 | 0.007 | 1 | 207 | Absent | 15 |
| Santa Maria T/O | 17.3 | 8.41 | 0.07 | 2.72 | | 0.63 | 0.09 | 64 | 84 | 1.1 | 0.007 | 1 | 207 | Absent | 306 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 17.3 | 8.30 | 0.07 | 1.83 | | 0.47 | 0.14 | 62 | 84 | 1.2 | 0.081 | 1 | 208 | Absent | |
| Vandenberg T/O | 16.6 | 8.25 | 0.06 | 1.93 | | 0.38 | 0.03 | 66 | 82 | 1.2 | 0.006 | 1 | 210 | Absent | 206 |
| Tank Size #7 | | | | | | | | | | | | | | | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 8.8 **MG**

*Samples Taken:* 03/16/2026

*Samples Analyzed:* 3/17/2026 2:12:00 PM

*Sampler:* James Thompson, Sean Rog

*Analyst:* Sean Rogers

***Comments:*** Chlorination system on at Tank 5.

*Report Generated:* 03/19/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, March 23, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | February Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 21.2 | 8.36 | 0.06 | 3.53 | | 0.72 | 0.01 | 60 | 76 | 0.8 | 0.005 | 1 | 201 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 18.8 | 8.35 | 0.08 | 3.13 | | 0.60 | 0.08 | 62 | 80 | 1.2 | 0.006 | 1 | 204 | Absent | |
| Chorro | 18.9 | 8.37 | 0.08 | 3.07 | | 0.55 | 0.04 | 64 | 82 | 1.2 | 0.006 | 1 | 205 | Absent | 134 |
| Lopez T/O | 19.0 | 8.40 | 0.06 | 2.94 | | 0.58 | 0.10 | 64 | 82 | 1.0 | 0.006 | 1 | 206 | Absent | 105 |
| Guadalupe T/O | 18.7 | 8.48 | 0.06 | 2.81 | | 0.66 | 0.10 | 66 | 82 | 1.0 | 0.009 | 1 | 207 | Absent | 15 |
| Santa Maria T/O | 18.7 | 8.47 | 0.06 | 2.81 | | 0.65 | 0.10 | 66 | 82 | 0.9 | 0.010 | 1 | 207 | Absent | 306 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 18.1 | 8.37 | 0.05 | 1.67 | | 0.38 | 0.11 | 66 | 82 | 1.1 | 0.087 | 1 | 210 | Absent | |
| Vandenberg T/O | 17.9 | 8.33 | 0.07 | 1.60 | | 0.30 | 0.03 | 68 | 82 | 1.1 | 0.008 | 1 | 212 | Absent | 206 |
| Tank Size #7 | | | | | | | | | | | | | | | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 9.4 **MG**

*Samples Taken:* 03/23/2026
*Samples Analyzed:* 3/26/2026 10:39:00 AM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 04/01/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, March 30, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | February Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 21.2 | 8.27 | 0.06 | 3.43 | | 0.68 | 0.01 | 66 | 80 | 0.6 | 0.004 | 1 | 204 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 20.0 | 8.35 | 0.06 | 3.17 | | 0.62 | 0.07 | 68 | 82 | 0.8 | 0.005 | 1 | 205 | Absent | |
| Chorro | 20.4 | 8.37 | 0.08 | 3.05 | | 0.61 | 0.05 | 70 | 84 | 0.8 | 0.005 | 1 | 205 | Absent | 134 |
| Lopez T/O | 20.5 | 8.41 | 0.07 | 3.04 | | 0.60 | 0.09 | 72 | 82 | 0.7 | 0.005 | 1 | 204 | Absent | 105 |
| Guadalupe T/O | 20.4 | 8.44 | 0.09 | 2.90 | | 0.64 | 0.08 | 74 | 80 | 0.6 | 0.012 | 1 | 205 | Absent | 15 |
| Santa Maria T/O | 20.1 | 8.44 | 0.07 | 2.77 | | 0.62 | 0.07 | 74 | 80 | 0.6 | 0.017 | 1 | 205 | Absent | 306 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 19.2 | 8.20 | 0.13 | 1.43 | | 0.35 | 0.12 | 74 | 80 | 0.8 | 0.117 | 1 | 205 | Absent | |
| Vandenberg T/O | 18.6 | 8.20 | 0.08 | 1.45 | | 0.28 | 0.04 | 74 | 82 | 0.8 | 0.007 | 1 | 208 | Absent | 206 |
| Tank Size #7 | | | | | | | | | | | | | | | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 12.2 **MG**

*Samples Taken:* 03/30/2026
*Samples Analyzed:* 3/31/2026 1:13:00 PM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 04/02/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, April 6, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | March Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 21.1 | 8.21 | 0.04 | 3.45 | | 0.75 | 0.05 | 64 | 80 | 0.7 | 0.006 | 1 | 206 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 18.9 | 8.33 | 0.09 | 3.24 | | 0.64 | 0.10 | 66 | 80 | 0.8 | 0.006 | 1 | 208 | Absent | |
| Chorro | 19.6 | 8.38 | 0.06 | 3.21 | | 0.61 | 0.08 | 70 | 80 | 0.7 | 0.006 | 1 | 210 | Absent | 130 |
| Lopez T/O | 19.9 | 8.38 | 0.05 | 3.11 | | 0.59 | 0.07 | 70 | 82 | 0.7 | 0.007 | 1 | 211 | Absent | 138 |
| Guadalupe T/O | 20.8 | 8.39 | 0.05 | 2.87 | | 0.66 | 0.10 | 72 | 82 | 0.6 | 0.018 | 1 | 212 | Absent | 18 |
| Santa Maria T/O | 21.1 | 8.35 | 0.06 | 2.88 | | 0.63 | 0.11 | 70 | 82 | 0.6 | 0.035 | 1 | 212 | Absent | 435 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 19.7 | 8.17 | 0.08 | 1.64 | | 0.32 | 0.12 | 68 | 82 | 0.7 | 0.121 | 1 | 210 | Absent | |
| Vandenberg T/O | 18.5 | 8.18 | 0.06 | 1.29 | | 0.26 | 0.06 | 68 | 82 | 0.7 | 0.009 | 1 | 212 | Absent | 257 |
| Tank Size #7 | | | | | | | | | | | | | | | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | | | | | | | | | | | | | | | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 12.3 **MG**

*Samples Taken:* 04/06/2026
*Samples Analyzed:* 4/8/2026 10:47:00 AM
*Sampler:* Adrian Arguilles, Sean Roger
*Analyst:* Sean Rogers

**Comments:** Chlorination system on at Tank 5.

*Report Generated:* 04/17/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, April 13, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | March Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 18.6 | 8.38 | 0.05 | 3.34 | | 0.69 | 0.00 | 66 | 80 | 0.5 | 0.006 | 1 | 213 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 18.5 | 8.32 | 0.05 | 2.72 | | 0.50 | 0.06 | 72 | 82 | 0.8 | 0.006 | 1 | 210 | Absent | |
| Chorro | 19.1 | 8.38 | 0.06 | 2.70 | | 0.54 | 0.10 | 70 | 82 | 0.8 | 0.005 | 1 | 209 | Absent | 130 |
| Lopez T/O | 19.1 | 8.47 | 0.06 | 2.68 | | 0.57 | 0.12 | 70 | 82 | 0.7 | 0.006 | 1 | 209 | Absent | 138 |
| Guadalupe T/O | 19.5 | 8.57 | 0.09 | 2.71 | | 0.66 | 0.14 | 70 | 82 | 0.7 | 0.012 | 1 | 210 | Absent | 18 |
| Santa Maria T/O | 19.6 | 8.53 | 0.07 | 2.67 | | 0.66 | 0.12 | 68 | 82 | 0.6 | 0.016 | 1 | 210 | Absent | 435 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 19.0 | 8.54 | 0.07 | 2.58 | | 0.62 | 0.14 | 68 | 84 | 0.6 | 0.038 | 1 | 210 | Absent | |
| Vandenberg T/O | 18.6 | 8.52 | 0.05 | 3.09 | | 0.60 | 0.03 | 70 | 84 | 0.6 | 0.015 | 1 | 212 | Absent | 257 |
| Tank Site #7 | 17.9 | 8.54 | 0.07 | 2.09 | | 0.41 | 0.00 | 68 | 84 | 0.6 | 0.009 | 1 | 217 | Absent | |
| Buellton T/O | 18.2 | 8.48 | 0.06 | 1.32 | | 0.25 | 0.00 | 66 | 84 | 0.7 | 0.007 | 1 | 218 | Absent | 0 |
| Solvang T/O | 17.2 | 8.39 | 0.36 | 1.02 | | 0.19 | 0.03 | 66 | 86 | 0.7 | 0.007 | 1 | 220 | Absent | 0 |
| Santa Ynex ID#1 T/O | 17.0 | 8.42 | 0.09 | 0.65 | | 0.15 | 0.04 | 64 | 86 | 0.8 | 0.014 | 1 | 224 | Absent | 0 |

**Average Plant Flow for Sample Week =** 5.3 **MG**

*Samples Taken:* 04/13/2026
*Samples Analyzed:* 4/16/2026 8:27:00 AM
*Sampler:* Cody Weinberg, Sean Roger
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 04/17/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, April 20, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | March Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 19.7 | 8.28 | 0.05 | 3.39 | | 0.71 | 0.02 | 72 | 88 | 0.5 | 0.005 | 1 | 233 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 18.8 | 8.38 | 0.05 | 3.12 | | 0.64 | 0.09 | 70 | 88 | 0.6 | 0.005 | 1 | 231 | Absent | |
| Chorro | 19.3 | 8.40 | 0.06 | 3.10 | | 0.56 | 0.04 | 70 | 88 | 0.6 | 0.007 | 1 | 229 | Absent | 130 |
| Lopez T/O | 19.6 | 8.40 | 0.06 | 3.06 | | 0.56 | 0.07 | 70 | 86 | 0.6 | 0.006 | 1 | 227 | Absent | 138 |
| Guadalupe T/O | 20.1 | 8.42 | 0.06 | 2.97 | | 0.65 | 0.11 | 68 | 86 | 0.5 | 0.019 | 1 | 221 | Absent | 18 |
| Santa Maria T/O | 20.5 | 8.38 | 0.06 | 2.86 | | 0.62 | 0.09 | 68 | 86 | 0.5 | 0.028 | 1 | 219 | Absent | 435 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 19.0 | 8.33 | 0.06 | 2.29 | | 0.46 | 0.10 | 68 | 84 | 0.5 | 0.074 | 1 | 218 | Absent | |
| Vandenberg T/O | 18.9 | 8.32 | 0.05 | 2.15 | | 0.39 | 0.03 | 70 | 84 | 0.5 | 0.008 | 1 | 220 | Absent | 257 |
| Tank Site #7 | 17.5 | 8.57 | 0.05 | 2.68 | | 0.52 | 0.00 | 68 | 84 | 0.6 | 0.009 | 1 | 213 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | 16.9 | 8.58 | 0.08 | 2.47 | | 0.52 | 0.04 | 66 | 84 | 0.6 | 0.008 | 1 | 213 | Absent | 0 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 0 |

**Average Plant Flow for Sample Week =** 11.7 **MG**

*Samples Taken:* 04/20/2026
*Samples Analyzed:* 4/23/2026 11:31:00 AM
*Sampler:* James Thompson, Sean Rog
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7. SYPP pumped 35.79 acre-feet to Lake Cachuma.

*Report Generated:* 05/01/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, April 27, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | March Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 17.8 | 8.33 | 0.05 | 3.73 | | 0.79 | 0.05 | 70 | 88 | 0.8 | 0.004 | 1 | 228 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 18.3 | 8.33 | 0.06 | 3.37 | | 0.63 | 0.05 | 76 | 90 | 0.5 | 0.005 | 1 | 231 | Absent | |
| Chorro | 19.2 | 8.40 | 0.06 | 3.32 | | 0.60 | 0.04 | 76 | 90 | 0.5 | 0.005 | 1 | 232 | Absent | 130 |
| Lopez T/O | 19.2 | 8.41 | 0.07 | 3.30 | | 0.70 | 0.13 | 76 | 90 | 0.4 | 0.006 | 1 | 232 | Absent | 138 |
| Guadalupe T/O | 19.9 | 8.39 | 0.09 | 3.15 | | 0.66 | 0.09 | 78 | 92 | 0.4 | 0.020 | 1 | 233 | Absent | 18 |
| Santa Maria T/O | 20.0 | 8.36 | 0.05 | 3.02 | | 0.64 | 0.09 | 80 | 92 | 0.4 | 0.029 | 1 | 233 | Absent | 435 |
| Golden State T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #5 | 19.7 | 8.25 | 0.05 | 2.37 | | 0.50 | 0.10 | 78 | 90 | 0.5 | 0.057 | 1 | 234 | Absent | |
| Vandenberg T/O | 19.3 | 8.24 | 0.09 | 2.45 | | 0.46 | 0.07 | 78 | 90 | 0.5 | 0.006 | 1 | 236 | Absent | 257 |
| Tank Site #7 | 18.6 | 8.32 | 0.04 | 2.07 | | 0.40 | 0.02 | 80 | 92 | 0.5 | 0.006 | 1 | 238 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | 18.8 | 8.36 | 0.05 | 1.95 | | 0.39 | 0.02 | 84 | 90 | 0.5 | 0.005 | 1 | 238 | Absent | 0 |
| Santa Ynex ID#1 T/O | 18.6 | 8.38 | 0.04 | 1.87 | | 0.39 | 0.01 | 74 | 90 | 0.5 | 0.006 | 1 | 238 | Absent | 0 |

**Average Plant Flow for Sample Week =** 14.7 **MG**

*Samples Taken:* 04/27/2026
*Samples Analyzed:* 4/30/2026 11:09:00 AM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 05/01/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, May 4, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | April Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 19.7 | 8.34 | 0.05 | 3.44 | | 0.73 | 0.03 | 66 | 88 | 0.4 | 0.005 | 1 | 236 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 19.6 | 8.41 | 0.05 | 3.33 | | 0.63 | 0.06 | 68 | 88 | 0.5 | 0.006 | 1 | 234 | Absent | |
| Chorro | 19.8 | 8.41 | 0.05 | 3.27 | | 0.61 | 0.06 | 68 | 86 | 0.5 | 0.005 | 1 | 232 | Absent | 121 |
| Lopez T/O | 20.0 | 8.41 | 0.04 | 3.24 | | 0.61 | 0.09 | 68 | 88 | 0.4 | 0.006 | 1 | 231 | Absent | 113 |
| Guadalupe T/O | 20.1 | 8.35 | 0.04 | 3.01 | | 0.64 | 0.10 | 70 | 88 | 0.4 | 0.022 | 1 | 230 | Absent | 14 |
| Santa Maria T/O | 19.9 | 8.31 | 0.04 | 2.81 | | 0.61 | 0.11 | 70 | 88 | 0.4 | 0.031 | 1 | 230 | Absent | 370 |
| Golden State T/O | | | | | | | | | | | | | | | 24 |
| Tank Site #5 | 19.3 | 8.19 | 0.06 | 2.09 | | 0.46 | 0.13 | 68 | 88 | 0.5 | 0.092 | 1 | 228 | Absent | |
| Vandenberg T/O | 19.1 | 8.18 | 0.09 | 2.25 | | 0.41 | 0.08 | 70 | 88 | 0.5 | 0.012 | 1 | 230 | Absent | 257 |
| Tank Site #7 | 19.1 | 8.22 | 0.05 | 1.80 | | 0.36 | 0.03 | 70 | 90 | 0.5 | 0.017 | 1 | 231 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 0 |
| Solvang T/O | 19.1 | 8.26 | 0.07 | 1.79 | | 0.37 | 0.01 | 70 | 90 | 0.5 | 0.009 | 1 | 233 | Absent | 31 |
| Santa Ynex ID#1 T/O | 19.1 | 8.28 | 0.07 | 1.79 | | 0.39 | 0.03 | 72 | 92 | 0.5 | 0.009 | 1 | 233 | Absent | 93 |

**Average Plant Flow for Sample Week =** 15.4 **MG**

*Samples Taken:* 05/04/2026
*Samples Analyzed:* 5/5/2026 2:54:00 PM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 05/07/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, May 11, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | April Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 24.5 | 8.34 | 0.05 | 3.53 | | 0.71 | 0.00 | 70 | 84 | 0.7 | 0.005 | 1 | 232 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 21.2 | 8.44 | 0.07 | 3.33 | | 0.60 | 0.07 | 70 | 86 | 0.6 | 0.005 | 1 | 235 | Absent | |
| Chorro | 21.1 | 8.45 | 0.10 | 3.25 | | 0.59 | 0.04 | 70 | 88 | 0.6 | 0.004 | 1 | 237 | Absent | 121 |
| Lopez T/O | 21.1 | 8.46 | 0.05 | 3.20 | | 0.59 | 0.07 | 72 | 88 | 0.5 | 0.006 | 1 | 237 | Absent | 113 |
| Guadalupe T/O | 21.1 | 8.43 | 0.07 | 3.01 | | 0.64 | 0.09 | 74 | 90 | 0.4 | 0.012 | 1 | 239 | Absent | 14 |
| Santa Maria T/O | 20.8 | 8.41 | 0.05 | 2.92 | | 0.59 | 0.08 | 72 | 90 | 0.4 | 0.016 | 1 | 239 | Absent | 370 |
| Golden State T/O | | | | | | | | | | | | | | | 24 |
| Tank Site #5 | 20.2 | 8.21 | 0.05 | 2.06 | | 0.39 | 0.10 | 70 | 90 | 0.5 | 0.064 | 1 | 239 | Absent | |
| Vandenberg T/O | 19.3 | 8.20 | 0.09 | 2.06 | | 0.33 | 0.02 | 70 | 90 | 0.5 | 0.005 | 1 | 241 | Absent | 257 |
| Tank Size #7 | 18.9 | 8.21 | 0.06 | 2.10 | | 0.37 | 0.00 | 68 | 90 | 0.5 | 0.015 | 1 | 241 | Absent | |
| Buellton T/O | 18.7 | 8.24 | 0.06 | 1.98 | | 0.37 | 0.02 | 68 | 90 | 0.5 | 0.014 | 1 | 242 | Absent | 0 |
| Solvang T/O | 18.4 | 8.26 | 0.07 | 1.93 | | 0.37 | 0.02 | 68 | 90 | 0.5 | 0.013 | 1 | 242 | Absent | 31 |
| Santa Ynex ID#1 T/O | 18.1 | 8.25 | 0.05 | 1.85 | | 0.35 | 0.01 | 68 | 92 | 0.5 | 0.012 | 1 | 242 | Absent | 93 |

**Average Plant Flow for Sample Week =** 14.7 **MG**

*Samples Taken:* 05/11/2026

*Samples Analyzed:* 5/12/2026 1:47:00 PM

*Sampler:* Adrian Arguilles, Sean Roger

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 05/15/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, May 18, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | April Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 24.1 | 8.32 | 0.05 | 3.46 | | 0.71 | 0.00 | 72 | 84 | 0.7 | 0.005 | 1 | 238 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 21.8 | 8.39 | 0.06 | 3.25 | | 0.58 | 0.06 | 76 | 86 | 0.6 | 0.005 | 1 | 232 | Absent | |
| Chorro | 22.2 | 8.43 | 0.06 | 3.16 | | 0.56 | 0.03 | 78 | 88 | 0.5 | 0.005 | 1 | 231 | Absent | 121 |
| Lopez T/O | 22.6 | 8.44 | 0.06 | 3.15 | | 0.59 | 0.09 | 78 | 88 | 0.4 | 0.007 | 1 | 230 | Absent | 113 |
| Guadalupe T/O | 23.1 | 8.43 | 0.05 | 3.02 | | 0.65 | 0.07 | 78 | 88 | 0.4 | 0.012 | 1 | 231 | Absent | 14 |
| Santa Maria T/O | 23.0 | 8.40 | 0.05 | 3.07 | | 0.64 | 0.07 | 80 | 88 | 0.4 | 0.013 | 1 | 231 | Absent | 370 |
| Golden State T/O | | | | | | | | | | | | | | | 24 |
| Tank Site #5 | 22.3 | 8.28 | 0.05 | 2.16 | | 0.46 | 0.09 | 82 | 88 | 0.4 | 0.064 | 1 | 232 | Absent | |
| Vandenberg T/O | 21.7 | 8.25 | 0.05 | 2.23 | | 0.40 | 0.04 | 80 | 90 | 0.4 | 0.014 | 1 | 234 | Absent | 257 |
| Tank Site #7 | 20.3 | 8.10 | 0.07 | 2.31 | | 0.39 | 0.04 | 76 | 90 | 0.6 | 0.007 | 1 | 241 | Absent | |
| Buellton T/O | 20.2 | 8.15 | 0.07 | 2.17 | | 0.43 | 0.06 | 78 | 90 | 0.6 | 0.009 | 1 | 241 | Absent | 0 |
| Solvang T/O | 18.9 | 8.16 | 0.06 | 1.99 | | 0.41 | 0.06 | 78 | 90 | 0.6 | 0.014 | 1 | 242 | Absent | 31 |
| Santa Ynex ID#1 T/O | 19.4 | 8.17 | 0.04 | 1.80 | | 0.37 | 0.05 | 76 | 90 | 0.6 | 0.009 | 1 | 242 | Absent | 93 |

**Average Plant Flow for Sample Week =** 16.3 **MG**

*Samples Taken:* 05/18/2026
*Samples Analyzed:* 5/19/2026 1:04:00 PM
*Sampler:* Cody Weinberg, Sean Roger
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 05/20/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Tuesday, May 26, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | April Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 21.0 | 8.34 | 0.06 | 3.53 | | 0.72 | 0.00 | 68 | 92 | 0.4 | 0.005 | 1 | 248 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 20.9 | 8.37 | 0.06 | 3.28 | | 0.64 | 0.03 | 72 | 90 | 0.6 | 0.005 | 1 | 249 | Absent | |
| Chorro | 21.1 | 8.45 | 0.07 | 3.23 | | 0.61 | 0.05 | 70 | 90 | 0.5 | 0.006 | 1 | 249 | Absent | 121 |
| Lopez T/O | 21.8 | 8.45 | 0.05 | 3.20 | | 0.69 | 0.07 | 70 | 90 | 0.5 | 0.006 | 1 | 249 | Absent | 113 |
| Guadalupe T/O | 22.1 | 8.48 | 0.05 | 3.08 | | 0.64 | 0.06 | 68 | 92 | 0.4 | 0.020 | 1 | 249 | Absent | 14 |
| Santa Maria T/O | 22.2 | 8.45 | 0.08 | 3.02 | | 0.63 | 0.08 | 68 | 90 | 0.4 | 0.031 | 1 | 249 | Absent | 370 |
| Golden State T/O | | | | | | | | | | | | | | | 24 |
| Tank Site #5 | 21.0 | 8.32 | 0.06 | 2.17 | | 0.47 | 0.13 | 68 | 90 | 0.5 | 0.071 | 1 | 249 | Absent | |
| Vandenberg T/O | 20.3 | 8.29 | 0.08 | 2.15 | | 0.41 | 0.04 | 70 | 90 | 0.5 | 0.005 | 1 | 250 | Absent | 257 |
| Tank Site #7 | 19.6 | 8.12 | 0.06 | 1.91 | | 0.35 | 0.03 | 70 | 92 | 0.8 | 0.003 | 1 | 247 | Absent | |
| Buellton T/O | 19.8 | 8.11 | 0.05 | 1.29 | | 0.28 | 0.09 | 72 | 92 | 0.8 | 0.025 | 1 | 249 | Absent | 0 |
| Solvang T/O | 19.0 | 8.08 | 0.06 | 0.52 | | 0.14 | 0.08 | 72 | 92 | 0.9 | 0.099 | 1 | 251 | Absent | 31 |
| Santa Ynez ID#1 T/O | | | | | | | | | | | | | | | 93 |

**Average Plant Flow for Sample Week =** 13.3 **MG**

*Samples Taken:* 05/26/2026
*Samples Analyzed:* 5/28/2026 12:47:00 PM
*Sampler:* James Thompson, Sean Rog
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 05/29/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, June 1, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | May Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 22.2 | 8.30 | 0.04 | 3.59 | | 0.73 | 0.01 | 72 | 92 | 0.5 | 0.004 | 1 | 247 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 19.8 | 8.33 | 0.06 | 3.27 | | 0.58 | 0.02 | 74 | 92 | 0.7 | 0.006 | 1 | 251 | Absent | |
| Chorro | 20.4 | 8.36 | 0.06 | 3.23 | | 0.55 | 0.03 | 72 | 94 | 0.6 | 0.005 | 1 | 252 | Absent | 135 |
| Lopez T/O | 20.8 | 8.37 | 0.04 | 3.18 | | 0.58 | 0.07 | 72 | 94 | 0.5 | 0.005 | 1 | 252 | Absent | 175 |
| Guadalupe T/O | 20.9 | 8.39 | 0.06 | 2.99 | | 0.60 | 0.05 | 72 | 92 | 0.4 | 0.019 | 1 | 253 | Absent | 20 |
| Santa Maria T/O | 20.8 | 8.35 | 0.07 | 2.85 | | 0.58 | 0.07 | 70 | 94 | 0.4 | 0.028 | 1 | 253 | Absent | 493 |
| Golden State T/O | | | | | | | | | | | | | | | 45 |
| Tank Site #5 | 20.2 | 8.29 | 0.06 | 2.30 | | 0.49 | 0.09 | 70 | 96 | 0.4 | 0.051 | 1 | 254 | Absent | |
| Vandenberg T/O | 20.0 | 8.28 | 0.07 | 2.41 | | 0.44 | 0.03 | 70 | 94 | 0.4 | 0.007 | 1 | 255 | Absent | 354 |
| Tank Site #7 | 19.8 | 8.38 | 0.05 | 2.37 | | 0.48 | 0.02 | 68 | 92 | 0.4 | 0.005 | 1 | 254 | Absent | |
| Buellton T/O | 19.7 | 8.37 | 0.05 | 2.04 | | 0.40 | 0.01 | 68 | 92 | 0.4 | 0.004 | 1 | 254 | Absent | 11 |
| Solvang T/O | 19.8 | 8.38 | 0.08 | 1.96 | | 0.39 | 0.00 | 68 | 92 | 0.4 | 0.005 | 1 | 254 | Absent | 57 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 178 |

**Average Plant Flow for Sample Week =** 16.0 **MG**

*Samples Taken:* 06/01/2026

*Samples Analyzed:* 6/4/2026 12:10:00 PM

*Sampler:* James Shaner, Sean Rogers

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7. SYPP pumped 48.5 acre-feet to Lake Cachuma.

*Report Generated:* 06/10/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, June 8, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | May Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 22.8 | 8.22 | 0.04 | 3.41 | | 0.68 | 0.00 | 74 | 90 | 0.5 | 0.004 | 1 | 250 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 22.0 | 8.42 | 0.05 | 3.25 | | 0.64 | 0.05 | 76 | 90 | 0.7 | 0.005 | 1 | 251 | Absent | |
| Chorro | 22.3 | 8.44 | 0.06 | 3.17 | | 0.56 | 0.06 | 78 | 90 | 0.7 | 0.005 | 1 | 250 | Absent | 135 |
| Lopez T/O | 22.8 | 8.45 | 0.07 | 3.13 | | 0.58 | 0.06 | 78 | 92 | 0.6 | 0.005 | 1 | 249 | Absent | 175 |
| Guadalupe T/O | 22.3 | 8.47 | 0.06 | 3.02 | | 0.63 | 0.08 | 76 | 90 | 0.6 | 0.022 | 1 | 249 | Absent | 20 |
| Santa Maria T/O | 22.2 | 8.43 | 0.08 | 2.82 | | 0.60 | 0.09 | 76 | 90 | 0.6 | 0.036 | 1 | 249 | Absent | 493 |
| Golden State T/O | | | | | | | | | | | | | | | 45 |
| Tank Site #5 | 21.6 | 8.35 | 0.06 | 2.19 | | 0.46 | 0.08 | 76 | 90 | 0.6 | 0.083 | 1 | 249 | Absent | |
| Vandenberg T/O | 21.2 | 8.32 | 0.07 | 2.22 | | 0.39 | 0.02 | 76 | 90 | 0.6 | 0.009 | 1 | 252 | Absent | 354 |
| Tank Site #7 | 20.0 | 8.32 | 0.05 | 2.06 | | 0.40 | 0.00 | 74 | 92 | 0.6 | 0.004 | 1 | 250 | Absent | |
| Buellton T/O | 19.8 | 8.33 | 0.06 | 1.98 | | 0.40 | 0.02 | 74 | 92 | 0.5 | 0.005 | 1 | 248 | Absent | 11 |
| Solvang T/O | 19.8 | 8.33 | 0.07 | 1.91 | | 0.37 | 0.00 | 74 | 92 | 0.5 | 0.004 | 1 | 249 | Absent | 57 |
| Santa Ynex ID#1 T/O | | | | | | | | | | | | | | | 178 |

**Average Plant Flow for Sample Week =** 16.0 **MG**

*Samples Taken:* 06/08/2026
*Samples Analyzed:* 6/9/2026 3:07:00 PM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7. SYPP pumped 43.72 acre-feet to Lake Cachuma.

*Report Generated:* 06/12/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, June 15, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | May Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 25.0 | 8.21 | 0.06 | 3.39 | | 0.68 | 0.01 | 76 | 90 | 0.7 | 0.004 | 1 | 239 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 24.0 | 8.42 | 0.08 | 3.22 | | 0.58 | 0.05 | 76 | 90 | 0.8 | 0.006 | 1 | 240 | Absent | |
| Chorro | 23.8 | 8.47 | 0.08 | 3.18 | | 0.56 | 0.04 | 76 | 92 | 0.8 | 0.005 | 1 | 240 | Absent | 135 |
| Lopez T/O | 24.0 | 8.46 | 0.08 | 3.15 | | 0.56 | 0.06 | 76 | 92 | 0.7 | 0.006 | 1 | 239 | Absent | 175 |
| Guadalupe T/O | 23.9 | 8.46 | 0.10 | 3.09 | | 0.63 | 0.07 | 74 | 92 | 0.6 | 0.014 | 1 | 239 | Absent | 20 |
| Santa Maria T/O | 23.5 | 8.44 | 0.08 | 3.00 | | 0.61 | 0.08 | 74 | 90 | 0.6 | 0.021 | 1 | 239 | Absent | 493 |
| Golden State T/O | | | | | | | | | | | | | | | 45 |
| Tank Site #5 | 22.9 | 8.32 | 0.08 | 2.32 | | 0.47 | 0.10 | 72 | 90 | 0.6 | 0.061 | 1 | 239 | Absent | |
| Vandenberg T/O | 22.3 | 8.33 | 0.09 | 2.40 | | 0.44 | 0.04 | 70 | 90 | 0.6 | 0.008 | 1 | 240 | Absent | 354 |
| Tank Site #7 | 21.5 | 8.37 | 0.07 | 2.43 | | 0.43 | 0.00 | 74 | 90 | 0.6 | 0.005 | 1 | 241 | Absent | |
| Buellton T/O | 21.3 | 8.38 | 0.08 | 2.31 | | 0.43 | 0.00 | 76 | 92 | 0.6 | 0.005 | 1 | 243 | Absent | 11 |
| Solvang T/O | 21.2 | 8.38 | 0.06 | 2.29 | | 0.42 | 0.00 | 74 | 92 | 0.6 | 0.005 | 1 | 244 | Absent | 57 |
| Santa Ynex ID#1 T/O | 20.6 | 8.39 | 0.10 | 2.22 | | 0.42 | 0.00 | 74 | 92 | 0.6 | 0.005 | 1 | 246 | Absent | 178 |

**Average Plant Flow for Sample Week =** 19.3 **MG**

*Samples Taken:* 06/15/2026
*Samples Analyzed:* 6/16/2026 3:21:00 PM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 06/17/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, June 22, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | May Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 23.8 | 8.42 | 0.08 | 3.42 | | 0.72 | 0.02 | 74 | 92 | 0.7 | 0.005 | 1 | 247 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 22.9 | 8.41 | 0.08 | 3.23 | | 0.57 | 0.03 | 74 | 90 | 0.8 | 0.006 | 1 | 246 | Absent | |
| Chorro | 23.3 | 8.43 | 0.07 | 3.13 | | 0.56 | 0.05 | 74 | 88 | 0.7 | 0.006 | 1 | 246 | Absent | 135 |
| Lopez T/O | 23.7 | 8.43 | 0.07 | 3.07 | | 0.55 | 0.05 | 76 | 88 | 0.6 | 0.006 | 1 | 244 | Absent | 175 |
| Guadalupe T/O | 23.6 | 8.46 | 0.10 | 2.95 | | 0.63 | 0.07 | 74 | 88 | 0.6 | 0.017 | 1 | 244 | Absent | 20 |
| Santa Maria T/O | 22.3 | 8.45 | 0.10 | 2.85 | | 0.59 | 0.06 | 72 | 90 | 0.6 | 0.020 | 1 | 243 | Absent | 493 |
| Golden State T/O | | | | | | | | | | | | | | | 45 |
| Tank Site #5 | 22.8 | 8.37 | 0.08 | 2.15 | | 0.44 | 0.08 | 72 | 90 | 0.7 | 0.070 | 1 | 241 | Absent | |
| Vandenberg T/O | 21.8 | 8.35 | 0.07 | 2.17 | | 0.39 | 0.01 | 72 | 92 | 0.7 | 0.008 | 1 | 243 | Absent | 354 |
| Tank Site #7 | 21.5 | 8.41 | 0.06 | 2.29 | | 0.39 | 0.00 | 74 | 90 | 0.7 | 0.006 | 1 | 242 | Absent | |
| Buellton T/O | 21.2 | 8.40 | 0.10 | 2.26 | | 0.40 | 0.00 | 74 | 88 | 0.7 | 0.006 | 1 | 243 | Absent | 11 |
| Solvang T/O | 21.2 | 8.39 | 0.08 | 1.96 | | 0.38 | 0.00 | 74 | 88 | 0.7 | 0.004 | 1 | 243 | Absent | 57 |
| Santa Ynex ID#1 T/O | 21.1 | 8.39 | 0.07 | 1.95 | | 0.37 | 0.00 | 76 | 88 | 0.7 | 0.004 | 1 | 243 | Absent | 178 |

**Average Plant Flow for Sample Week =** 18.5 **MG**

*Samples Taken:* 06/22/2026

*Samples Analyzed:* 6/23/2026 2:14:00 PM

*Sampler:* Cody Weinberg, Sean Roger

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 06/26/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, June 29, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | May Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 24.4 | 8.39 | 0.07 | 3.44 | | 0.68 | 0.00 | 74 | 90 | 0.5 | 0.005 | 1 | 249 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 23.0 | 8.46 | 0.07 | 3.36 | | 0.61 | 0.03 | 74 | 90 | 0.9 | 0.006 | 1 | 250 | Absent | |
| Chorro | 22.7 | 8.48 | 0.05 | 3.27 | | 0.69 | 0.05 | 74 | 90 | 0.8 | 0.005 | 1 | 250 | Absent | 135 |
| Lopez T/O | 23.8 | 8.48 | 0.07 | 3.23 | | 0.71 | 0.06 | 72 | 90 | 0.7 | 0.005 | 1 | 250 | Absent | 175 |
| Guadalupe T/O | 23.2 | 8.51 | 0.06 | 3.11 | | 0.63 | 0.05 | 72 | 90 | 0.6 | 0.012 | 1 | 249 | Absent | 20 |
| Santa Maria T/O | 23.0 | 8.49 | 0.05 | 3.01 | | 0.61 | 0.07 | 72 | 92 | 0.5 | 0.017 | 1 | 249 | Absent | 493 |
| Golden State T/O | | | | | | | | | | | | | | | 45 |
| Tank Site #5 | 22.6 | 8.34 | 0.05 | 2.34 | | 0.47 | 0.08 | 70 | 90 | 0.5 | 0.044 | 1 | 249 | Absent | |
| Vandenberg T/O | 22.1 | 8.33 | 0.07 | 2.22 | | 0.40 | 0.01 | 70 | 90 | 0.5 | 0.006 | 1 | 251 | Absent | 354 |
| Tank Site #7 | 21.7 | 8.35 | 0.07 | 2.03 | | 0.35 | 0.00 | 70 | 90 | 0.5 | 0.004 | 1 | 249 | Absent | |
| Buellton T/O | 21.6 | 8.35 | 0.06 | 1.90 | | 0.36 | 0.00 | 70 | 88 | 0.6 | 0.005 | 1 | 249 | Absent | 11 |
| Solvang T/O | 21.6 | 8.34 | 0.08 | 1.85 | | 0.35 | 0.00 | 72 | 88 | 0.5 | 0.003 | 1 | 249 | Absent | 57 |
| Santa Ynex ID#1 T/O | 21.6 | 8.34 | 0.07 | 1.87 | | 0.35 | 0.00 | 72 | 90 | 0.5 | 0.005 | 1 | 249 | Absent | 178 |

**Average Plant Flow for Sample Week =** 19.3 **MG**

*Samples Taken:* 06/29/2026
*Samples Analyzed:* 7/1/2026 1:12:00 PM
*Sampler:* James Thompson, Dustin Pit
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 07/02/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, July 6, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | June Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 25.0 | 8.39 | 0.05 | 3.58 | | 0.73 | 0.00 | 72 | 88 | 0.5 | 0.005 | 1 | 247 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 22.7 | 8.37 | 0.07 | 3.28 | | 0.59 | 0.04 | 74 | 88 | 0.9 | 0.005 | 1 | 248 | Absent | |
| Chorro | 23.0 | 8.42 | 0.08 | 3.22 | | 0.59 | 0.05 | 74 | 88 | 0.8 | 0.005 | 1 | 250 | Absent | 133 |
| Lopez T/O | 23.5 | 8.45 | 0.10 | 3.24 | | 0.61 | 0.06 | 74 | 90 | 0.7 | 0.005 | 1 | 251 | Absent | 162 |
| Guadalupe T/O | 22.9 | 8.47 | 0.06 | 3.18 | | 0.70 | 0.08 | 72 | 90 | 0.6 | 0.008 | 1 | 252 | Absent | 24 |
| Santa Maria T/O | 22.9 | 8.45 | 0.07 | 3.17 | | 0.69 | 0.08 | 72 | 90 | 0.5 | 0.011 | 1 | 252 | Absent | 537 |
| Golden State T/O | | | | | | | | | | | | | | | 52 |
| Tank Site #5 | 22.6 | 8.32 | 0.10 | 2.54 | | 0.54 | 0.12 | 72 | 92 | 0.5 | 0.061 | 1 | 255 | Absent | |
| Vandenberg T/O | 22.2 | 8.35 | 0.10 | 2.73 | | 0.51 | 0.01 | 74 | 92 | 0.5 | 0.006 | 1 | 254 | Absent | 346 |
| Tank Site #7 | 21.9 | 8.28 | 0.10 | 2.26 | | 0.43 | 0.00 | 74 | 90 | 0.5 | 0.005 | 1 | 255 | Absent | |
| Buellton T/O | 22.3 | 8.30 | 0.08 | 2.16 | | 0.42 | 0.01 | 72 | 90 | 0.6 | 0.004 | 1 | 255 | Absent | 30 |
| Solvang T/O | 22.1 | 8.30 | 0.11 | 2.18 | | 0.42 | 0.00 | 72 | 90 | 0.5 | 0.004 | 1 | 255 | Absent | 69 |
| Santa Ynex ID#1 T/O | 21.8 | 8.30 | 0.09 | 2.25 | | 0.44 | 0.00 | 72 | 92 | 0.5 | 0.005 | 1 | 255 | Absent | 314 |

**Average Plant Flow for Sample Week =** 20.2 **MG**

*Samples Taken:* 07/06/2026
*Samples Analyzed:* 7/8/2026 3:10:00 PM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 07/10/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, July 13, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | June Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 26.6 | 8.55 | 0.11 | 3.60 | | 0.71 | 0.01 | 72 | 80 | 0.5 | 0.005 | 1 | 218 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 24.7 | 8.53 | 0.11 | 3.25 | | 0.61 | 0.05 | 72 | 82 | 0.7 | 0.005 | 1 | 235 | Absent | |
| Chorro | 25.0 | 8.60 | 0.10 | 3.25 | | 0.57 | 0.02 | 72 | 84 | 0.6 | 0.006 | 1 | 240 | Absent | 133 |
| Lopez T/O | 25.1 | 8.59 | 0.11 | 3.20 | | 0.60 | 0.07 | 70 | 86 | 0.5 | 0.005 | 1 | 243 | Absent | 162 |
| Guadalupe T/O | 24.6 | 8.56 | 0.09 | 3.13 | | 0.66 | 0.05 | 70 | 88 | 0.4 | 0.009 | 1 | 250 | Absent | 24 |
| Santa Maria T/O | 24.4 | 8.55 | 0.08 | 3.11 | | 0.65 | 0.05 | 70 | 90 | 0.4 | 0.011 | 1 | 251 | Absent | 537 |
| Golden State T/O | | | | | | | | | | | | | | | 52 |
| Tank Site #5 | 23.8 | 8.44 | 0.11 | 2.59 | | 0.53 | 0.08 | 70 | 92 | 0.4 | 0.038 | 1 | 255 | Absent | |
| Vandenberg T/O | 23.6 | 8.40 | 0.08 | 2.65 | | 0.48 | 0.00 | 70 | 92 | 0.4 | 0.005 | 1 | 258 | Absent | 346 |
| Tank Site #7 | 22.9 | 8.35 | 0.07 | 2.17 | | 0.39 | 0.00 | 70 | 92 | 0.4 | 0.004 | 1 | 258 | Absent | |
| Buellton T/O | 22.9 | 8.33 | 0.07 | 2.02 | | 0.38 | 0.00 | 68 | 92 | 0.4 | 0.005 | 1 | 257 | Absent | 30 |
| Solvang T/O | 22.8 | 8.33 | 0.09 | 2.07 | | 0.39 | 0.00 | 68 | 92 | 0.4 | 0.004 | 1 | 255 | Absent | 69 |
| Santa Ynex ID#1 T/O | 22.7 | 8.33 | 0.12 | 2.05 | | 0.39 | 0.00 | 68 | 90 | 0.4 | 0.004 | 1 | 255 | Absent | 314 |

**Average Plant Flow for Sample Week =** 20.9 **MG**

*Samples Taken:* 07/13/2026
*Samples Analyzed:* 7/14/2026 1:42:00 PM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 07/24/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, July 20, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | June Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 27.7 | 8.37 | 0.10 | 3.61 | | 0.72 | 0.00 | 68 | 72 | 0.6 | 0.005 | 1 | 188 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 25.8 | 8.55 | 0.09 | 3.38 | | 0.59 | 0.03 | 74 | 72 | 0.9 | 0.006 | 1 | 193 | Absent | |
| Chorro | 26.2 | 8.52 | 0.10 | 3.28 | | 0.58 | 0.06 | 74 | 74 | 0.8 | 0.006 | 1 | 192 | Absent | 133 |
| Lopez T/O | 26.5 | 8.52 | 0.08 | 3.24 | | 0.58 | 0.05 | 72 | 74 | 0.8 | 0.005 | 1 | 192 | Absent | 162 |
| Guadalupe T/O | 25.9 | 8.51 | 0.09 | 3.21 | | 0.69 | 0.07 | 72 | 74 | 0.7 | 0.006 | 1 | 193 | Absent | 24 |
| Santa Maria T/O | 25.5 | 8.47 | 0.09 | 3.25 | | 0.67 | 0.05 | 72 | 76 | 0.7 | 0.006 | 1 | 193 | Absent | 537 |
| Golden State T/O | | | | | | | | | | | | | | | 52 |
| Tank Site #5 | 24.4 | 8.52 | 0.07 | 2.84 | | 0.63 | 0.09 | 74 | 76 | 0.7 | 0.015 | 1 | 195 | Absent | |
| Vandenberg T/O | 23.7 | 8.50 | 0.08 | 3.18 | | 0.60 | 0.00 | 72 | 76 | 0.7 | 0.007 | 1 | 197 | Absent | 346 |
| Tank Size #7 | 22.9 | 8.47 | 0.09 | 2.78 | | 0.49 | 0.00 | 72 | 78 | 0.7 | 0.004 | 1 | 206 | Absent | |
| Buellton T/O | 21.7 | 8.44 | 0.09 | 2.58 | | 0.50 | 0.00 | 72 | 78 | 0.7 | 0.004 | 1 | 207 | Absent | 30 |
| Solvang T/O | 22.6 | 8.41 | 0.10 | 2.49 | | 0.51 | 0.01 | 72 | 80 | 0.7 | 0.005 | 1 | 207 | Absent | 69 |
| Santa Ynex ID#1 T/O | 21.9 | 8.42 | 0.09 | 2.64 | | 0.49 | 0.00 | 72 | 80 | 0.7 | 0.006 | 1 | 207 | Absent | 314 |

**Average Plant Flow for Sample Week =** 22.0 **MG**

*Samples Taken:* 07/20/2026

*Samples Analyzed:* 7/23/2026 12:58:00 PM

*Sampler:* David Bazzell, Sean Rogers

*Analyst:* Sean Rogers

**Comments:**

*Report Generated:* 07/24/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, July 27, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | June Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 27.7 | 8.41 | 0.05 | 3.12 | | 0.59 | 0.00 | 68 | 70 | 0.5 | 0.004 | 1 | 165 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 26.5 | 8.47 | 0.09 | 2.81 | | 0.50 | 0.04 | 68 | 68 | 0.7 | 0.005 | 1 | 171 | Absent | |
| Chorro | 26.7 | 8.47 | 0.10 | 2.73 | | 0.48 | 0.05 | 68 | 68 | 0.7 | 0.006 | 1 | 171 | Absent | 133 |
| Lopez T/O | 27.2 | 8.49 | 0.07 | 2.74 | | 0.51 | 0.06 | 68 | 68 | 0.6 | 0.005 | 1 | 170 | Absent | 162 |
| Guadalupe T/O | 25.5 | 8.52 | 0.06 | 2.77 | | 0.58 | 0.05 | 70 | 70 | 0.6 | 0.005 | 1 | 171 | Absent | 24 |
| Santa Maria T/O | 25.1 | 8.50 | 0.10 | 2.76 | | 0.57 | 0.05 | 70 | 70 | 0.5 | 0.005 | 1 | 171 | Absent | 537 |
| Golden State T/O | | | | | | | | | | | | | | | 52 |
| Tank Site #5 | 25.6 | 8.52 | 0.06 | 2.67 | | 0.58 | 0.06 | 70 | 68 | 0.5 | 0.007 | 1 | 171 | Absent | |
| Vandenberg T/O | 24.3 | 8.52 | 0.07 | 2.92 | | 0.57 | 0.01 | 68 | 68 | 0.5 | 0.007 | 1 | 171 | Absent | 346 |
| Tank Size #7 | 23.7 | 8.51 | 0.06 | 2.94 | | 0.57 | 0.01 | 68 | 70 | 0.5 | 0.004 | 1 | 173 | Absent | |
| Buellton T/O | 23.8 | 8.48 | 0.06 | 3.09 | | 0.55 | 0.00 | 68 | 70 | 0.5 | 0.005 | 1 | 174 | Absent | 30 |
| Solvang T/O | | 8.49 | 0.09 | 2.82 | | 0.56 | 0.02 | 68 | 70 | 0.5 | 0.005 | 1 | 174 | Absent | 69 |
| Santa Ynex ID#1 T/O | | 8.49 | 0.07 | 2.68 | | 0.56 | 0.00 | 68 | 70 | 0.5 | 0.004 | 1 | 175 | Absent | 314 |

**Average Plant Flow for Sample Week =** 24.8 **MG**

*Samples Taken:* 07/27/2026
*Samples Analyzed:* 7/28/2026 2:10:00 PM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 07/30/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, August 3, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | July Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 28.1 | 8.41 | 0.06 | 3.00 | | 0.59 | 0.01 | 64 | 64 | 0.5 | 0.004 | 1 | 148 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 26.9 | 8.47 | 0.07 | 2.73 | | 0.51 | 0.05 | 72 | 64 | 0.7 | 0.006 | 1 | 151 | Absent | |
| Chorro | 26.8 | 8.52 | 0.06 | 2.72 | | 0.49 | 0.05 | 70 | 64 | 0.7 | 0.005 | 1 | 152 | Absent | 153 |
| Lopez T/O | 27.3 | 8.53 | 0.05 | 2.72 | | 0.49 | 0.04 | 68 | 66 | 0.6 | 0.005 | 1 | 152 | Absent | 156 |
| Guadalupe T/O | 25.3 | 8.56 | 0.06 | 2.78 | | 0.58 | 0.05 | 68 | 64 | 0.6 | 0.005 | 1 | 152 | Absent | 25 |
| Santa Maria T/O | 25.1 | 8.56 | 0.06 | 2.63 | | 0.58 | 0.06 | 68 | 64 | 0.5 | 0.005 | 1 | 153 | Absent | 750 |
| Golden State T/O | | | | | | | | | | | | | | | 65 |
| Tank Site #5 | 25.3 | 8.52 | 0.07 | 2.56 | | 0.55 | 0.06 | 68 | 66 | 0.5 | 0.008 | 1 | 154 | Absent | |
| Vandenberg T/O | 24.4 | 8.52 | 0.06 | 2.76 | | 0.52 | 0.00 | 68 | 64 | 0.5 | 0.005 | 1 | 156 | Absent | 348 |
| Tank Site #7 | 23.2 | 8.56 | 0.06 | 2.79 | | 0.50 | 0.00 | 66 | 64 | 0.4 | 0.004 | 1 | 156 | Absent | |
| Buellton T/O | 24.0 | 8.56 | 0.08 | 2.62 | | 0.51 | 0.00 | 66 | 66 | 0.5 | 0.004 | 1 | 155 | Absent | 31 |
| Solvang T/O | 24.0 | 8.58 | 0.07 | 2.66 | | 0.50 | 0.01 | 66 | 64 | 0.5 | 0.005 | 1 | 155 | Absent | 84 |
| Santa Ynex ID#1 T/O | 23.9 | 8.59 | 0.07 | 2.61 | | 0.49 | 0.00 | 68 | 66 | 0.5 | 0.006 | 1 | 156 | Absent | 468 |

**Average Plant Flow for Sample Week =** 23.7 **MG**

*Samples Taken:* 08/03/2026
*Samples Analyzed:* 8/6/2026 10:17:00 AM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7. SYPP pumped 39.7 acre-feet to Lake Cachuma.

*Report Generated:* 08/07/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, August 10, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | July Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 28.7 | 8.35 | 0.06 | 2.96 | | 0.59 | 0.01 | 60 | 60 | 0.3 | 0.005 | 1 | 141 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 26.7 | 8.43 | 0.08 | 2.78 | | 0.50 | 0.03 | 64 | 60 | 0.5 | 0.006 | 1 | 145 | Absent | |
| Chorro | 26.8 | 8.47 | 0.06 | 2.74 | | 0.49 | 0.04 | 64 | 60 | 0.5 | 0.005 | 1 | 145 | Absent | 153 |
| Lopez T/O | 27.1 | 8.46 | 0.06 | 2.72 | | 0.51 | 0.05 | 62 | 62 | 0.4 | 0.004 | 1 | 145 | Absent | 156 |
| Guadalupe T/O | 26.2 | 8.45 | 0.05 | 2.65 | | 0.57 | 0.05 | 62 | 62 | 0.4 | 0.005 | 1 | 145 | Absent | 25 |
| Santa Maria T/O | 25.6 | 8.46 | 0.07 | 2.71 | | 0.57 | 0.05 | 62 | 62 | 0.3 | 0.005 | 1 | 146 | Absent | 750 |
| Golden State T/O | | | | | | | | | | | | | | | 65 |
| Tank Site #5 | 25.6 | 8.50 | 0.06 | 2.62 | | 0.58 | 0.08 | 62 | 64 | 0.4 | 0.012 | 1 | 146 | Absent | |
| Vandenberg T/O | 25.1 | 8.52 | 0.10 | 2.83 | | 0.56 | 0.00 | 62 | 62 | 0.3 | 0.008 | 1 | 146 | Absent | 348 |
| Tank Size #7 | 24.6 | 8.53 | 0.07 | 2.64 | | 0.52 | 0.01 | 64 | 62 | 0.3 | 0.005 | 1 | 148 | Absent | |
| Buellton T/O | 24.3 | 8.52 | 0.07 | 2.63 | | 0.51 | 0.01 | 62 | 62 | 0.3 | 0.005 | 1 | 149 | Absent | 31 |
| Solvang T/O | 24.4 | 8.52 | 0.05 | 2.54 | | 0.50 | 0.00 | 62 | 60 | 0.4 | 0.006 | 1 | 149 | Absent | 84 |
| Santa Ynex ID#1 T/O | 24.0 | 8.52 | 0.07 | 2.33 | | 0.51 | 0.02 | 64 | 62 | 0.4 | 0.006 | 1 | 149 | Absent | 468 |

**Average Plant Flow for Sample Week =** 23.0 **MG**

*Samples Taken:* 08/10/2026
*Samples Analyzed:* 8/11/2026 3:27:00 PM
*Sampler:* Cody Weinberg, Sean Roger
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 08/18/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, August 17, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | July Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 26.9 | 8.37 | 0.08 | 3.30 | | 0.68 | 0.04 | 58 | 58 | 0.3 | 0.005 | 1 | 138 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 25.5 | 8.43 | 0.06 | 3.18 | | 0.58 | 0.06 | 62 | 58 | 0.5 | 0.008 | 1 | 140 | Absent | |
| Chorro | 25.5 | 8.49 | 0.08 | 3.17 | | 0.58 | 0.06 | 60 | 58 | 0.5 | 0.006 | 1 | 141 | Absent | 153 |
| Lopez T/O | 26.0 | 8.49 | 0.06 | 3.15 | | 0.58 | 0.06 | 60 | 60 | 0.4 | 0.006 | 1 | 141 | Absent | 156 |
| Guadalupe T/O | 25.8 | 8.52 | 0.06 | 3.10 | | 0.65 | 0.05 | 60 | 60 | 0.4 | 0.006 | 1 | 141 | Absent | 25 |
| Santa Maria T/O | 25.8 | 8.51 | 0.06 | 2.96 | | 0.64 | 0.04 | 58 | 62 | 0.3 | 0.005 | 1 | 141 | Absent | 750 |
| Golden State T/O | | | | | | | | | | | | | | | 65 |
| Tank Site #5 | 25.1 | 8.48 | 0.08 | 2.72 | | 0.56 | 0.07 | 58 | 62 | 0.3 | 0.012 | 1 | 141 | Absent | |
| Vandenberg T/O | 25.0 | 8.46 | 0.07 | 2.82 | | 0.53 | 0.00 | 58 | 62 | 0.3 | 0.006 | 1 | 142 | Absent | 348 |
| Tank Site #7 | 25.3 | 8.50 | 0.10 | 2.53 | | 0.48 | 0.00 | 60 | 60 | 0.3 | 0.005 | 1 | 142 | Absent | |
| Buellton T/O | 25.3 | 8.50 | 0.06 | 2.54 | | 0.48 | 0.00 | 60 | 60 | 0.3 | 0.004 | 1 | 142 | Absent | 31 |
| Solvang T/O | 25.2 | 8.50 | 0.05 | 2.52 | | 0.48 | 0.01 | 60 | 62 | 0.3 | 0.005 | 1 | 141 | Absent | 84 |
| Santa Ynex ID#1 T/O | 25.0 | 8.52 | 0.05 | 2.52 | | 0.48 | 0.01 | 60 | 60 | 0.3 | 0.005 | 1 | 141 | Absent | 468 |

**Average Plant Flow for Sample Week =** 20.9 **MG**

*Samples Taken:* 08/17/2026
*Samples Analyzed:* 8/18/2026 3:07:00 PM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems were on at Tank 5 and Tank7.

*Report Generated:* 08/20/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, August 24, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Free | NH3-N (mg/L) Total | Free | Alkalinity mg/L as CaCO3 | Hardness | Nitrate mg/L as N | Nitrite | TON | TDS | Coliform | July Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 27.6 | 8.30 | 0.05 | 3.16 | | 0.63 | 0.01 | 60 | 56 | 0.5 | 0.005 | 1 | 138 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 26.5 | 8.37 | 0.07 | 3.00 | | 0.56 | 0.07 | 62 | 56 | 0.5 | 0.005 | 1 | 138 | Absent | |
| Chorro | 26.7 | 8.47 | 0.05 | 3.00 | | 0.51 | 0.06 | 62 | 58 | 0.4 | 0.006 | 1 | 139 | Absent | 153 |
| Lopez T/O | 27.0 | 8.46 | 0.06 | 2.97 | | 0.54 | 0.06 | 64 | 58 | 0.4 | 0.005 | 1 | 139 | Absent | 156 |
| Guadalupe T/O | 25.9 | 8.45 | 0.07 | 2.89 | | 0.60 | 0.05 | 64 | 58 | 0.3 | 0.005 | 1 | 139 | Absent | 25 |
| Santa Maria T/O | 26.3 | 8.47 | 0.08 | 2.83 | | 0.59 | 0.05 | 62 | 60 | 0.3 | 0.006 | 1 | 139 | Absent | 750 |
| Golden State T/O | | | | | | | | | | | | | | | 65 |
| Tank Site #5 | 24.7 | 8.51 | 0.06 | 2.78 | | 0.55 | 0.05 | 64 | 58 | 0.3 | 0.015 | 1 | 140 | Absent | |
| Vandenberg T/O | 24.3 | 8.51 | 0.07 | 2.96 | | 0.55 | 0.01 | 62 | 58 | 0.3 | 0.011 | 1 | 141 | Absent | 348 |
| Tank Site #7 | 23.9 | 8.54 | 0.07 | 2.75 | | 0.50 | 0.00 | 62 | 58 | 0.3 | 0.007 | 1 | 139 | Absent | |
| Buellton T/O | 24.2 | 8.51 | 0.06 | 2.85 | | 0.49 | 0.00 | 64 | 58 | 0.3 | 0.008 | 1 | 139 | Absent | 31 |
| Solvang T/O | 23.7 | 8.50 | 0.07 | 2.43 | | 0.46 | 0.01 | 64 | 58 | 0.3 | 0.005 | 1 | 139 | Absent | 84 |
| Santa Ynex ID#1 T/O | 23.6 | 8.51 | 0.05 | 1.96 | | 0.45 | 0.01 | 64 | 56 | 0.3 | 0.004 | 1 | 139 | Absent | 468 |

**Average Plant Flow for Sample Week =** 21.7 **MG**

*Samples Taken:* 08/24/2026
*Samples Analyzed:* 8/25/2026 1:59:00 PM
*Sampler:* Adrian Arguilles, Sean Roger
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 08/27/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, August 31, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | July Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 25.2 | 8.36 | 0.04 | 3.34 | | 0.67 | 0.02 | 58 | 56 | 0.4 | 0.004 | 1 | 140 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 25.0 | 8.39 | 0.05 | 3.16 | | 0.58 | 0.05 | 62 | 56 | 0.5 | 0.005 | 1 | 142 | Absent | |
| Chorro | 25.6 | 8.46 | 0.06 | 3.11 | | 0.59 | 0.06 | 60 | 56 | 0.4 | 0.005 | 1 | 142 | Absent | 153 |
| Lopez T/O | 26.2 | 8.47 | 0.06 | 3.08 | | 0.55 | 0.06 | 60 | 58 | 0.4 | 0.005 | 1 | 143 | Absent | 156 |
| Guadalupe T/O | 25.3 | 8.45 | 0.06 | 2.95 | | 0.65 | 0.08 | 60 | 58 | 0.3 | 0.004 | 1 | 144 | Absent | 25 |
| Santa Maria T/O | 25.5 | 8.43 | 0.05 | 3.02 | | 0.63 | 0.04 | 58 | 58 | 0.3 | 0.005 | 1 | 144 | Absent | 750 |
| Golden State T/O | | | | | | | | | | | | | | | 65 |
| Tank Site #5 | 25.3 | 8.47 | 0.06 | 2.86 | | 0.59 | 0.05 | 58 | 56 | 0.3 | 0.009 | 1 | 144 | Absent | |
| Vandenberg T/O | 24.7 | 8.46 | 0.07 | 3.04 | | 0.59 | 0.03 | 58 | 58 | 0.3 | 0.007 | 1 | 145 | Absent | 348 |
| Tank Site #7 | 24.3 | 8.52 | 0.14 | 2.84 | | 0.56 | 0.03 | 60 | 60 | 0.3 | 0.006 | 1 | 145 | Absent | |
| Buellton T/O | 24.3 | 8.51 | 0.10 | 2.83 | | 0.53 | 0.00 | 58 | 58 | 0.3 | 0.005 | 1 | 144 | Absent | 31 |
| Solvang T/O | 23.9 | 8.50 | 0.09 | 2.83 | | 0.53 | 0.00 | 60 | 58 | 0.3 | 0.004 | 1 | 145 | Absent | 84 |
| Santa Ynex ID#1 T/O | 23.6 | 8.52 | 0.05 | 2.68 | | 0.53 | 0.02 | 60 | 60 | 0.3 | 0.004 | 1 | 145 | Absent | 468 |

**Average Plant Flow for Sample Week =** 21.5 **MG**

*Samples Taken:* 08/31/2026

*Samples Analyzed:* 9/1/2026 3:08:00 PM

*Sampler:* Cody Weinberg, Sean Roger

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 09/03/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Tuesday, September 8, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | August Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 24.8 | 8.43 | 0.06 | 3.33 | | 0.68 | 0.03 | 58 | 56 | 0.4 | 0.005 | 1 | 143 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 24.4 | 8.43 | 0.07 | 3.10 | | 0.55 | 0.05 | 64 | 56 | 0.3 | 0.004 | 1 | 144 | Absent | |
| Chorro | 25.1 | 8.46 | 0.05 | 3.05 | | 0.56 | 0.04 | 62 | 58 | 0.3 | 0.005 | 1 | 143 | Absent | 146 |
| Lopez T/O | 25.5 | 8.48 | 0.04 | 3.02 | | 0.54 | 0.07 | 60 | 58 | 0.3 | 0.005 | 1 | 143 | Absent | 156 |
| Guadalupe T/O | 25.0 | 8.51 | 0.10 | 2.97 | | 0.61 | 0.04 | 60 | 58 | 0.3 | 0.005 | 1 | 143 | Absent | 30 |
| Santa Maria T/O | 25.6 | 8.53 | 0.06 | 2.95 | | 0.61 | 0.05 | 60 | 60 | 0.3 | 0.005 | 1 | 143 | Absent | 828 |
| Golden State T/O | | | | | | | | | | | | | | | 54 |
| Tank Site #5 | 24.0 | 8.54 | 0.05 | 2.76 | | 0.56 | 0.04 | 62 | 58 | 0.3 | 0.015 | 1 | 143 | Absent | |
| Vandenberg T/O | 24.0 | 8.51 | 0.05 | 2.95 | | 0.56 | 0.00 | 60 | 56 | 0.3 | 0.010 | 1 | 143 | Absent | 350 |
| Tank Site #7 | 23.6 | 8.50 | 0.08 | 2.84 | | 0.53 | 0.00 | 58 | 58 | 0.3 | 0.006 | 1 | 143 | Absent | |
| Buellton T/O | 23.5 | 8.51 | 0.06 | 2.81 | | 0.54 | 0.00 | 60 | 58 | 0.3 | 0.005 | 1 | 143 | Absent | 33 |
| Solvang T/O | 23.4 | 8.52 | 0.05 | 2.81 | | 0.53 | 0.00 | 60 | 58 | 0.3 | 0.004 | 1 | 143 | Absent | 92 |
| Santa Ynex ID#1 T/O | 23.5 | 8.53 | 0.06 | 2.73 | | 0.53 | 0.00 | 58 | 58 | 0.3 | 0.004 | 1 | 143 | Absent | 457 |

**Average Plant Flow for Sample Week =** 21.7 **MG**

*Samples Taken:* 09/08/2026
*Samples Analyzed:* 9/9/2026 3:03:00 PM
*Sampler:* James Thompson, Sean Rog
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 09/10/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, September 14, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | August Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 25.3 | 8.38 | 0.05 | 2.93 | | 0.64 | 0.01 | 60 | 58 | 0.3 | 0.005 | 1 | 144 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 25.0 | 8.38 | 0.08 | 3.12 | | 0.65 | 0.06 | 66 | 58 | 0.5 | 0.005 | 1 | 146 | Absent | |
| Chorro | 26.2 | 8.44 | 0.07 | 3.06 | | 0.63 | 0.04 | 64 | 58 | 0.4 | 0.005 | 1 | 146 | Absent | 146 |
| Lopez T/O | 26.3 | 8.46 | 0.09 | 3.07 | | 0.64 | 0.05 | 60 | 60 | 0.4 | 0.004 | 1 | 146 | Absent | 156 |
| Guadalupe T/O | 25.6 | 8.52 | 0.06 | 3.00 | | 0.64 | 0.06 | 62 | 60 | 0.3 | 0.005 | 1 | 147 | Absent | 30 |
| Santa Maria T/O | 25.4 | 8.49 | 0.05 | 2.95 | | 0.60 | 0.03 | 62 | 60 | 0.3 | 0.006 | 1 | 147 | Absent | 828 |
| Golden State T/O | | | | | | | | | | | | | | | 54 |
| Tank Site #5 | 25.0 | 8.49 | 0.06 | 2.80 | | 0.57 | 0.06 | 60 | 60 | 0.3 | 0.019 | 1 | 147 | Absent | |
| Vandenberg T/O | 24.6 | 8.44 | 0.05 | 3.00 | | 0.54 | 0.00 | 60 | 62 | 0.3 | 0.007 | 1 | 148 | Absent | 350 |
| Tank Site #7 | 23.5 | 8.47 | 0.10 | 2.87 | | 0.52 | 0.00 | 60 | 60 | 0.3 | 0.005 | 1 | 149 | Absent | |
| Buellton T/O | 23.5 | 8.47 | 0.08 | 2.79 | | 0.52 | 0.00 | 62 | 58 | 0.3 | 0.005 | 1 | 148 | Absent | 33 |
| Solvang T/O | 23.5 | 8.48 | 0.06 | 2.86 | | 0.52 | 0.00 | 62 | 58 | 0.3 | 0.005 | 1 | 148 | Absent | 92 |
| Santa Ynez ID#1 T/O | 23.3 | 8.50 | 0.05 | 2.74 | | 0.51 | 0.00 | 64 | 60 | 0.3 | 0.005 | 1 | 148 | Absent | 457 |

**Average Plant Flow for Sample Week =** 22.8 **MG**

*Samples Taken:* 09/14/2026
*Samples Analyzed:* 9/15/2026 3:26:00 PM
*Sampler:* James Shaner
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 09/18/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, September 21, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | August Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 23.4 | 8.31 | 0.06 | 3.26 | | 0.69 | 0.03 | 60 | 62 | 0.3 | 0.005 | 1 | 157 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 24.4 | 8.38 | 0.05 | 3.18 | | 0.66 | 0.05 | 66 | 62 | 0.4 | 0.005 | 1 | 156 | Absent | |
| Chorro | 24.1 | 8.44 | 0.09 | 3.17 | | 0.62 | 0.07 | 64 | 60 | 0.4 | 0.005 | 1 | 157 | Absent | 146 |
| Lopez T/O | 24.1 | 8.45 | 0.06 | 3.12 | | 0.58 | 0.06 | 62 | 62 | 0.3 | 0.004 | 1 | 156 | Absent | 156 |
| Guadalupe T/O | 24.1 | 8.47 | 0.06 | 3.09 | | 0.64 | 0.03 | 64 | 64 | 0.3 | 0.006 | 1 | 156 | Absent | 30 |
| Santa Maria T/O | 24.0 | 8.46 | 0.09 | 2.96 | | 0.64 | 0.05 | 64 | 62 | 0.3 | 0.007 | 1 | 156 | Absent | 828 |
| Golden State T/O | | | | | | | | | | | | | | | 54 |
| Tank Site #5 | 23.7 | 8.39 | 0.05 | 2.75 | | 0.55 | 0.06 | 64 | 62 | 0.3 | 0.027 | 1 | 156 | Absent | |
| Vandenberg T/O | 23.5 | 8.37 | 0.06 | 2.86 | | 0.52 | 0.00 | 62 | 60 | 0.3 | 0.006 | 1 | 156 | Absent | 350 |
| Tank Site #7 | 24.2 | 8.42 | 0.05 | 2.75 | | 0.51 | 0.00 | 62 | 60 | 0.3 | 0.004 | 1 | 151 | Absent | |
| Buellton T/O | 24.3 | 8.44 | 0.07 | 2.73 | | 0.55 | 0.00 | 62 | 62 | 0.3 | 0.005 | 1 | 151 | Absent | 33 |
| Solvang T/O | 24.3 | 8.44 | 0.08 | 2.69 | | 0.51 | 0.00 | 60 | 60 | 0.3 | 0.005 | 1 | 151 | Absent | 92 |
| Santa Ynex ID#1 T/O | 24.2 | 8.46 | 0.06 | 2.62 | | 0.50 | 0.00 | 60 | 62 | 0.3 | 0.005 | 1 | 151 | Absent | 457 |

**Average Plant Flow for Sample Week =** 21.7 **MG**

*Samples Taken:* 09/21/2026
*Samples Analyzed:* 9/22/2026 2:50:00 PM
*Sampler:* David Bazzell, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 09/24/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, September 28, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | August Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 23.1 | 8.31 | 0.07 | 3.10 | | 0.62 | 0.00 | 62 | 62 | 0.3 | 0.004 | 1 | 165 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 23.1 | 8.35 | 0.05 | 2.97 | | 0.60 | 0.04 | 66 | 62 | 0.3 | 0.006 | 1 | 161 | Absent | |
| Chorro | 23.8 | 8.37 | 0.06 | 2.93 | | 0.52 | 0.02 | 64 | 62 | 0.2 | 0.004 | 1 | 161 | Absent | 146 |
| Lopez T/O | 24.1 | 8.36 | 0.09 | 2.87 | | 0.51 | 0.03 | 64 | 64 | 0.2 | 0.004 | 1 | 160 | Absent | 156 |
| Guadalupe T/O | 24.1 | 8.38 | 0.06 | 3.09 | | 0.56 | 0.05 | 62 | 64 | 0.2 | 0.006 | 1 | 160 | Absent | 30 |
| Santa Maria T/O | 24.0 | 8.39 | 0.08 | 2.96 | | 0.55 | 0.05 | 62 | 62 | 0.2 | 0.008 | 1 | 160 | Absent | 828 |
| Golden State T/O | | | | | | | | | | | | | | | 54 |
| Tank Site #5 | 23.7 | 8.39 | 0.06 | 2.75 | | 0.48 | 0.06 | 62 | 60 | 0.3 | 0.031 | 1 | 159 | Absent | |
| Vandenberg T/O | 23.5 | 8.37 | 0.09 | 2.86 | | 0.44 | 0.00 | 64 | 62 | 0.3 | 0.006 | 1 | 160 | Absent | 350 |
| Tank Site #7 | 24.2 | 8.39 | 0.08 | 2.75 | | 0.42 | 0.00 | 64 | 64 | 0.3 | 0.005 | 1 | 160 | Absent | |
| Buellton T/O | 24.3 | 8.39 | 0.07 | 2.73 | | 0.43 | 0.00 | 62 | 62 | 0.3 | 0.003 | 1 | 159 | Absent | 33 |
| Solvang T/O | 24.3 | 8.38 | 0.06 | 2.69 | | 0.42 | 0.00 | 62 | 62 | 0.3 | 0.005 | 1 | 159 | Absent | 92 |
| Santa Ynex ID#1 T/O | 24.2 | 8.39 | 0.07 | 2.62 | | 0.42 | 0.00 | 62 | 62 | 0.3 | 0.004 | 1 | 159 | Absent | 457 |

**Average Plant Flow for Sample Week =** 22.0 **MG**

*Samples Taken:* 09/28/2026

*Samples Analyzed:* 9/29/2026 2:10:00 PM

*Sampler:* David Bazzell, Sean Rogers

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 10/01/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, October 5, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | September Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 25.1 | 8.29 | 0.05 | 3.22 | | 0.64 | 0.00 | 66 | 68 | 0.3 | 0.005 | 1 | 185 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 23.8 | 8.37 | 0.07 | 3.07 | | 0.55 | 0.04 | 74 | 66 | 0.5 | 0.005 | 1 | 185 | Absent | |
| Chorro | 24.4 | 8.41 | 0.06 | 2.98 | | 0.54 | 0.04 | 70 | 66 | 0.5 | 0.005 | 1 | 184 | Absent | 133 |
| Lopez T/O | 24.5 | 8.42 | 0.07 | 2.98 | | 0.53 | 0.03 | 68 | 66 | 0.4 | 0.005 | 1 | 184 | Absent | 276 |
| Guadalupe T/O | 24.1 | 8.43 | 0.05 | 2.93 | | 0.59 | 0.03 | 68 | 68 | 0.3 | 0.008 | 1 | 183 | Absent | 29 |
| Santa Maria T/O | 24.0 | 8.41 | 0.07 | 2.90 | | 0.57 | 0.04 | 68 | 68 | 0.3 | 0.010 | 1 | 183 | Absent | 785 |
| Golden State T/O | | | | | | | | | | | | | | | 64 |
| Tank Site #5 | 23.6 | 8.34 | 0.07 | 2.53 | | 0.50 | 0.06 | 66 | 66 | 0.3 | 0.027 | 1 | 179 | Absent | |
| Vandenberg T/O | 23.6 | 8.33 | 0.05 | 2.67 | | 0.47 | 0.01 | 66 | 66 | 0.3 | 0.006 | 1 | 178 | Absent | 315 |
| Tank Site #7 | 23.1 | 8.36 | 0.07 | 2.52 | | 0.46 | 0.00 | 68 | 66 | 0.3 | 0.005 | 1 | 173 | Absent | |
| Buellton T/O | 23.0 | 8.35 | 0.06 | 2.42 | | 0.45 | 0.00 | 66 | 64 | 0.3 | 0.004 | 1 | 171 | Absent | 30 |
| Solvang T/O | 22.1 | 8.36 | 0.06 | 2.40 | | 0.45 | 0.00 | 66 | 64 | 0.3 | 0.004 | 1 | 170 | Absent | 89 |
| Santa Ynex ID#1 T/O | 22.6 | 8.37 | 0.08 | 2.38 | | 0.45 | 0.00 | 66 | 64 | 0.3 | 0.005 | 1 | 170 | Absent | 378 |

**Average Plant Flow for Sample Week =** 22.1 **MG**

*Samples Taken:* 10/05/2026

*Samples Analyzed:* 10/6/2026 3:02:00 PM

*Sampler:* James Shaner, Sean Rogers

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 10/08/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, October 12, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | September Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 22.2 | 8.41 | 0.07 | 3.15 | | 0.60 | 0.01 | 68 | 70 | 0.4 | 0.005 | 1 | 203 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 23.2 | 8.42 | 0.06 | 3.01 | | 0.55 | 0.04 | 74 | 70 | 0.4 | 0.006 | 1 | 201 | Absent | |
| Chorro | 24.8 | 8.47 | 0.06 | 2.95 | | 0.54 | 0.03 | 72 | 70 | 0.3 | 0.006 | 1 | 201 | Absent | 133 |
| Lopez T/O | 24.4 | 8.48 | 0.06 | 2.93 | | 0.53 | 0.05 | 70 | 70 | 0.3 | 0.005 | 1 | 200 | Absent | 276 |
| Guadalupe T/O | 23.5 | 8.48 | 0.11 | 2.91 | | 0.58 | 0.02 | 70 | 70 | 0.3 | 0.011 | 1 | 199 | Absent | 29 |
| Santa Maria T/O | 23.7 | 8.47 | 0.05 | 2.86 | | 0.57 | 0.01 | 70 | 72 | 0.3 | 0.015 | 1 | 199 | Absent | 785 |
| Golden State T/O | | | | | | | | | | | | | | | 64 |
| Tank Site #5 | 22.4 | 8.40 | 0.07 | 2.33 | | 0.48 | 0.05 | 70 | 74 | 0.3 | 0.048 | 1 | 198 | Absent | |
| Vandenberg T/O | 22.5 | 8.41 | 0.09 | 2.46 | | 0.46 | 0.00 | 70 | 72 | 0.3 | 0.012 | 1 | 199 | Absent | 315 |
| Tank Site #7 | 22.3 | 8.48 | 0.05 | 2.46 | | 0.47 | 0.00 | 68 | 70 | 0.3 | 0.006 | 1 | 195 | Absent | |
| Buellton T/O | 22.5 | 8.49 | 0.06 | 2.38 | | 0.48 | 0.00 | 70 | 70 | 0.3 | 0.006 | 1 | 195 | Absent | 30 |
| Solvang T/O | 22.3 | 8.49 | 0.06 | 2.40 | | 0.46 | 0.00 | 70 | 70 | 0.3 | 0.006 | 1 | 194 | Absent | 89 |
| Santa Ynex ID#1 T/O | 22.2 | 8.49 | 0.05 | 2.35 | | 0.47 | 0.00 | 70 | 68 | 0.3 | 0.006 | 1 | 194 | Absent | 378 |

**Average Plant Flow for Sample Week =** 20.2 **MG**

*Samples Taken:* 10/12/2026

*Samples Analyzed:* 10/13/2026 3:21:00 PM

*Sampler:* James Thompson, Sean Rog

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7.

*Report Generated:* 10/16/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, October 19, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | September Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 22.1 | 7.80 | 0.04 | 1.80 | | 0.03 | 0.00 | 64 | 72 | 0.3 | 0.005 | 1 | 217 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 21.2 | 8.30 | 0.07 | 2.75 | | 0.55 | 0.07 | 74 | 72 | 0.4 | 0.005 | 1 | 215 | Absent | |
| Chorro | 22.2 | 8.34 | 0.07 | 2.71 | | 0.50 | 0.04 | 72 | 74 | 0.4 | 0.005 | 1 | 215 | Absent | 133 |
| Lopez T/O | 22.4 | 8.34 | 0.07 | 2.68 | | 0.51 | 0.06 | 70 | 76 | 0.4 | 0.006 | 1 | 215 | Absent | 276 |
| Guadalupe T/O | 22.2 | 8.34 | 0.07 | 2.61 | | 0.51 | 0.08 | 70 | 74 | 0.3 | 0.013 | 1 | 214 | Absent | 29 |
| Santa Maria T/O | 22.3 | 8.33 | 0.13 | 2.55 | | 0.49 | 0.05 | 70 | 74 | 0.3 | 0.019 | 1 | 214 | Absent | 785 |
| Golden State T/O | | | | | | | | | | | | | | | 64 |
| Tank Site #5 | 21.9 | 8.26 | 0.07 | 2.05 | | 0.41 | 0.07 | 70 | 74 | 0.4 | 0.046 | 1 | 213 | Absent | |
| Vandenberg T/O | 21.4 | 8.26 | 0.08 | 2.18 | | 0.37 | 0.02 | 68 | 72 | 0.4 | 0.006 | 1 | 213 | Absent | 315 |
| Tank Site #7 | 21.8 | 8.31 | 0.06 | 2.23 | | 0.39 | 0.00 | 70 | 72 | 0.3 | 0.004 | 1 | 212 | Absent | |
| Buellton T/O | 22.1 | 8.31 | 0.06 | 2.17 | | 0.38 | 0.00 | 68 | 74 | 0.3 | 0.005 | 1 | 211 | Absent | 30 |
| Solvang T/O | 22.1 | 8.32 | 0.05 | 2.12 | | 0.37 | 0.00 | 68 | 76 | 0.3 | 0.004 | 1 | 211 | Absent | 89 |
| Santa Ynex ID#1 T/O | 22.0 | 8.34 | 0.09 | 2.09 | | 0.36 | 0.00 | 68 | 72 | 0.3 | 0.004 | 1 | 211 | Absent | 378 |

**Average Plant Flow for Sample Week =** 18.7 **MG**

*Samples Taken:* 10/19/2026
*Samples Analyzed:* 10/22/2026 1:10:00 PM
*Sampler:* James Shaner, Sean Rogers
*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7. PPWTP switched to free chlorine on October 19, 2026.

*Report Generated:* 10/30/2026

# Central Coast Water Authority

## Process Control Benchsheet

**Date:** Monday, October 26, 2026

| | Temp °C | pH | NTU | Chlorine (mg/L) Total | Chlorine (mg/L) Free | NH3-N (mg/L) Total | NH3-N (mg/L) Free | Alkalinity mg/L as CaCO3 | Hardness mg/L as CaCO3 | Nitrate mg/L as N | Nitrite mg/L as N | TON | TDS | Coliform | September Deliveries |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Treated Water Tanks | 19.5 | 8.03 | 0.06 | 3.49 | | | | 70 | 80 | 0.6 | 0.005 | 1 | 230 | Absent | |
| Shandon T/O | | | | | | | | | | | | | | | 0 |
| Tank Site #2 | 20.1 | 8.17 | 0.05 | 2.89 | | | | 72 | 80 | 0.4 | 0.004 | 1 | 225 | Absent | |
| Chorro | 21.5 | 8.26 | 0.07 | 2.62 | | | | 70 | 82 | 0.4 | 0.004 | 1 | 225 | Absent | 133 |
| Lopez T/O | | | | | | | | | | | | | | | 276 |
| Guadalupe T/O | 22.2 | 8.34 | 0.08 | 1.96 | | | | 70 | 82 | 0.3 | 0.004 | 1 | 223 | Absent | 29 |
| Santa Maria T/O | | | | | | | | | | | | | | | 785 |
| Golden State T/O | | | | | | | | | | | | | | | 64 |
| Tank Site #5 | 21.8 | 8.34 | 0.14 | 1.88 | | | | 70 | 80 | 0.3 | 0.003 | 1 | 222 | Absent | |
| Vandenberg T/O | 21.4 | 8.34 | 0.08 | 2.57 | | | | 72 | 80 | 0.3 | 0.004 | 1 | 225 | Absent | 315 |
| Tank Site #7 | 21.9 | 8.37 | 0.04 | 2.69 | | | | 72 | 80 | 0.4 | 0.004 | 1 | 226 | Absent | |
| Buellton T/O | | | | | | | | | | | | | | | 30 |
| Solvang T/O | | | | | | | | | | | | | | | 89 |
| Santa Ynex ID#1 T/O | 22.1 | 8.39 | 0.09 | 2.00 | | | | 74 | 78 | 0.3 | 0.003 | 1 | 226 | Absent | 378 |

**Average Plant Flow for Sample Week =** 9.7 **MG**

*Samples Taken:* 10/26/2026

*Samples Analyzed:* 10/27/2026 2:31:00 PM

*Sampler:* James Shaner, Sean Rogers

*Analyst:* Sean Rogers

**Comments:** Chlorination systems on at Tank 5 and Tank 7. PPWTP switched to free chlorine on October 19, 2026.

*Report Generated:* 10/30/2026